


INSTALLATION INSTRUCTION OF X CONNECTOR

Turn electricity off at fuse box or circuit breaker box.

1. Remove cover from X connector. Place track with Ceiling Plate attached to Outlet Box and mark on ceiling or wall the position of the track mounting holes (**CAUTION** : Embossed arrow mark on X connector should point to debossed polarity line on track for proper installation after assembly).
2. Fasten Ceiling Plate to Outlet Box with two screws. Pull wires from Box thru open hole of X connector.
- 3 Cut ans strip wires from Box and fasten BK supply wire to Brass terminal; WH supply wire to Nickel-Plated terminal ;Green Ground supply wire to Green Ground terminal by rotating the screws.
4. Push excess wires back to into Outlet Box and recap the cover by screw.



SAVE THESE INSTRUCTIONS

NOTE : Put BK and WH jumper wire as the picture shows to complete the circuit in this X connector.

