

PARTS AND HARDWARE.

PARTS LIST

NO.	DESCRIPTION	IMAGE	Q'TY
P1	ТОР	\bigcirc	1
P2	LEG		2
P3	STRETCHER		1
P4	T- CLIP	-	2

HARDWARES LIST

NO.	DESCRIPTION	IMAGE	Q'TY
H1	HEX BOLT	8	16
H2	SPANNER	and the second s	1
НЗ	WASHER	0	16
H4	L-ANGLE		8
H6	ALLEN BOLT	0)	6
H7	ALLEN KEY	V	1

NOTES.

Thank you for purchasing this quality product! Be sure to check all packing material carefully for small part that may have come loose inside the carton during shipping.

CAUTION: The item is heavy, assembly should be performed by two people.



