

PARTS AND HARDWARE.


	NO.	DESCRIPTION	IMAGE	Q′TY	
	P1	TOP SHELF		1	
	P2	BASE CABINET		1	
	HARDWARE LIST				

NO.	DESCRIPTION	IMAGE	Q'TY
Н1	BOLT M6 x 20	Juunun	4
H2	BOLT M8 x 20	Juunun	8
Н3	SPRING WASHER M8	Ø	8
H4	WASHER M8	0	8
H5	ALLEN KEY M4		1
H6	WALL ANCHOR	Carried	2
H7	SCREW M6 x 60	Guunnun	2
H8	METAL PLATE		2
Н9	METAL PLATE	a a a a a a a a a a a a a a a a a a a	2
H10	SCREW M4 x 40	Guunnus	2
Н11	SCREW DRIVER		NOT PROVIDE


NOTES.

Thank you for purchasing this quality product! Be sure to check all packing material carefully for small part that may have come loose inside the carton during shipping.

CAUTION: The item is heavy, assembly should be performed by two people.



(P2)



STEP 4.

STEP 2.

