


Assembly Instructions for 3021, 3022

We recommend installation of this fixture be done by a licensed electrican. Turn off power at the main fuse or circuit breaker box. DO NOT EXCEED RECOMMENDED WATTAGE!

**Actual parts may vary slightly depending upon the model



- 1. Remove the parts carefully from the box before discarding the carton
- 2. Attach the cross bar to the outlet box with ground screw facing out.
- 3. Thread the 8/32 threads into the cross bar; about 1/4" should extended beyond the back plate.
- 4. Fasten ground wire to green screw, Fasten lead wire (or white wire) with ridges to the white wire. Use wire nut to fasten it.
- 5. Fasten smooth (or black wire) lead wire to the black wire in the box & use nut to fasten it.
- 6. Install bulbs (not included)
- 7. Place fixture over the ceiling (without installing glass and ring) outlet box going through 8/32 threads
- 8. Secure the fixture & 3 light lamp cluster with ball nut.
- 9. Place glass shade on the canopy, followed by ring on the shade with 3 holes on the shade aligning with holes on L bracket and ring. Remove thumb screw from the L bracket. Use thumb screw to lock the shade and ring to L bracket. Two person is highly recommended for this step. Glass can be removed for cleaning.
- 10. Restore circuit breaker

*Never touch the sconce/shade while power is on. To change bulb, allow 15 minutes for fixture to cool down.

www.jvidesigns.com